


<b>Picture of task/equipment:</b> 	<b>Task:</b>	Dumping waste with Vestil JMD-1000
	<b>Name of Shop or Dept:</b>	CSUDH Campus - Sustainability
	<b>Job Title(s):</b>	Sustainability, Mover
	<b>Analyzed by:</b>	M. Williams
	<b>Date:</b>	5/11/2022

**Required PPE:**

Work Boots



Gloves



Hearing Protection



Safety Glasses



Safety Vest




Mask/Face Protection



**Required/Recommended Trainings:**

IIPP

Equipment Specific

TASK	HAZARDS	CONTROLS
Dumping waste in the Vestil JMD-1000 tote dumper  	Struck By's Pinch Lacerations	<ul style="list-style-type: none"> <li>D Inspect the tote for damage before each lift. Do not attempt to pick up the tote unless it is in good condition.</li> <li>D Always have the floor lock engaged solidly with the floor surface when the dumper is in operation.</li> <li>D Lock wheels before operation</li> <li>D Verify that the tote is engaged and held securely by the dumper before proceeding to raise the tote.</li> <li>D Always watch the dumper and the tote carefully when the dumper is in operation.</li> <li>D Stand away from the side of the dumper when it is in operation. Stay clear of any potential pinch and shear points.</li> <li>D Be alert to the possibility of splashing or flying material when dumping loads.</li> <li>D Do not use the dumper if any damage or unusual noise is observed.</li> <li>D When moving the dumper for charging, raise handlebar and push dumper to charging station</li> <li>D Ensure wheels are locked when charging</li> </ul>